



SERVICE BULLETIN

SEGA Service Department
45133 Industrial Drive
Fremont, Ca. 94538

<http://www.seusevice.com>
Phone: 415.701.6580
Fax: 415.701.6594

Field Service Bulletin Wild Riders Service Advisory Notice!!!! Verify Input Control Operation

SYMPTOM: Player controls may respond improperly, and players will not be able to perform all the tricks and functions of the game due to improper speed range etc....

SOLUTION: Perform 'Volume Adjustments' (See FIG A). Be sure to move all inputs (Steering / Brake / Accelerator) to their mechanical limits while in this test. Use Service Switch to move the arrow to 'Exit with Save' then press the Test Button. Exit out of the Test Mode fully and go to the Game Mode. Play game to verify proper operation.

VOLUME ADJUSTMENTS			
	MIN	MAX	NEUTRAL
HANDLEBAR	[00H] (00H)	[FFH] (FFH)	[80H] (80H)
ACCELERATOR	[00H] (00H)	[FFH] (FFH)	[00H]
FRONT BRAKE	[00H] (00H)	[FFH] (FFH)	[00H]
REAR BRAKE	[00H] (00H)	[FFH] (FFH)	[00H]

EXIT WITH SAVE

->EXIT WITHOUT SAVE

SELECT WITH SERVICE BUTTON
AND PRESS TEST BUTTON

FIG A.



IMPORTANT!

Not following the directions provided herein may cause your game to malfunction. All electrical work should be performed by the site's Serviceman or Technician.

If you have any questions please contact the SEGA Service Department at the numbers given above.