


SERVICE BULLETIN

June 5th, 2007


GAME NAME: CYCRAFT (INITIAL D3, CLUB KART)

SUBJECT: • SAFETY LINK, WRONG WAY OF MOUNTING

Please DO NOT mount SAFETY LINK wrong way that cause of TOSHIBA Motor Drive Board issue. Game works fine while but stop at error when Cockpit goes uper position.



This is NG. (Short part of Safety link come to Actuator side then joint part is hitting to actuator.)



This is GOOD!!!