



Manual Amendment

These changes apply to Touchmaster Infinity manual 16-60068.2-101. In some cases part numbers have changed or were in error. In other cases, part descriptions do not appear in existing manual at all.

Page No.	Part Description	Correct Part Number		
Service - 9	Touchscreen Replacement	See enclosed sheet 16-11151		
Parts - 2	Cabinet Assembly (Rear View) There are two Machine Screws 4-40x3/8 P-FH to hold line filter.	4004-01041-06		
Parts - 4	HD Bracket Assembly	A-23343		
Parts - 5	Marquee Artwork on Top Cover	31-3630		
Parts - 6	Monitor-Touchscreen Assembly	See enclosed sheet 16-11151		
Parts - 6	Foam Pad on Base Assembly	23-6821.1		
Parts - 7	Coin Door Support Bracket	04-12723.1		
Parts - 8	CPU Board Assembly	See illustration on other side		

MARS DBV SETTING (A-E2411U5E)

	DIP 1	DIP 2	DIP 3	DIP 4	DIP 5	DIP 6	DIP 7	DIP 8
Domestic	Off	On	On	On	On	On	Off	Off
New Jersey	Off	On	On	On	Off	Off	Off	On
Function	2 way	2 way	High Security	\$1 accept	\$2 accept	\$5 accept	1 pulse per dollar	Harness enable

midway amusement games IIc

3401 north california avenue chicago, illinois 60618-5899

http://www.midway.com

MARS DBV SETTING (VN2511U5)

	DIP 1	DIP 2	DIP 3	DIP 4	DIP 5	DIP 6	DIP 7	DIP 8
Domestic	Off	On	On	On	On	On	Off	Off
New Jersey	Off	On	On	On	Off	Off	Off	Off
Function	2 way	2 way	High Security	\$1 accept	\$2 accept	\$5 accept	Long pulse	Long Pulse

CPU BOARD ASSEMBLY (A-23341)

