



August 3, 1998

SERVICE BULLETIN

If you have any questions please direct them to the service department
45133 Industrial Dr. Phone: 650-802-1750
Fremont Ca., 94538 Fax: 650-802-1754

This is to inform you of a possible problem concerning Daytona 2 USA 'STD versions'.

PROBLEM: No music during Game Play. Possible incorrect sounds from Front-Back speakers.
CAUSE: CN7 and CN8 (JST Connectors) reversed at Game BD Filter.

SOLUTION: Reverse/switch positions of CN7 and CN8 to correspond to correct wiring setup.

