

## **AFTER BURNER SUPER DX COIN DOOR SECTION ASSEMBLY MANUAL**


**There are 4 terminal connectors and 2 screws**

**A: 4 terminal connectors for Coin harness.**


**B: 2 screws for Coin meter bracket.**

**A**

**B**



**1. Remove the coin meter from cash box bracket.**




**2. Mount the coin meter on the "L" bracket and mount it on cashbox (metal) with 2 screws(B)**




- 3. Cut out the 4 wires beside terminal connectors**  
Coin 1: Blue and Black  
Coin 2: Orange and Black

Do not use this harness.  
(Use for option DBA power)




- 4. Put in 4 new terminal connectors(A)**



Lamp 1, Lamp 2 harness

Coin 1, Coin 2 harness

Coin meter harness



- 5. Connect the each connector.**  
(Coin 1, Coin 2, Lamp 1, Lamp 2 and Coin meter.)